

	Type	Hits	Search Text	DBs
1	BRS	970	361/93.6	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
2	BRS	1105	differential near (relay relays)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
3	BRS	41	differential near (relay relays) and feeder	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
4	BRS	1202	differential same (feeders feeder)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
5	BRS	46	differential same (feeder feeders) same (ct or (current adj transformer\$))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
6	BRS	4	(differential same (feeder feeders) same (ct or (current adj transformer\$))) same (parallel paralleled)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
7	BRS	970	361/93.6	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
8	BRS	272	361/36	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
9	BRS	12	4,538,195	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
10	BRS	0	differential adj (relay relays) and mov	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
11	BRS	997	differential adj (relay relays)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
12	BRS	0	differential adj (relay relays) and mov	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
13	BRS	178	current adj transformer\$ and mov	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
14	BRS	0	current adj transformer\$ near mov	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
15	BRS	56	current adj transformer\$ same mov	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
16	BRS	6	mov near shorting	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
17	BRS	13	mov near resistor	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB

	<b>Time Stamp</b>	<b>Comments</b>	<b>Error Definition</b>	<b>Errors</b>
1	2004/06/07 09:28			0
2	2004/06/07 09:29			0
3	2004/06/07 10:08			0
4	2004/06/07 10:08			0
5	2004/06/07 10:10			0
6	2004/06/07 10:11			0
7	2004/06/07 10:13			0
8	2004/06/07 13:16			0
9	2004/06/14 12:09			0
10	2004/06/14 12:10			0
11	2004/06/14 12:10			0
12	2004/06/14 12:10			0
13	2004/06/14 12:11			0
14	2004/06/14 12:11			0
15	2004/06/14 13:06			0
16	2004/06/14 13:32			0
17	2004/06/14 14:18			0

	Type	Hits	Search Text	DBs
18	BRS	773	361/64 or 361/66	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
19	BRS	109	differential and (361/64 or 361/66)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
20	BRS	4	4,089,033	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
21	BRS	3	("2548625"   "3259802"   "4025821").PN.	USPAT
22	BRS	13	circuit adj breaker and current adj transformer near feed	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
23	BRS	35	flux adj transfer near (device relay)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
24	BRS	12	flux adj transfer near (device relay) and circuit adj breaker	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
25	BRS	4	5,560,923	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
26	BRS	3	5,670,923	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
27	BRS	223	4,672,501	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
28	BRS	18	3,761,778	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
29	BRS	0	4,876,625 and differential	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
30	BRS	4	5,982,597	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
31	BRS	28328	circuit adj breaker and current transformer same varistor	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
32	BRS	28479	circuit adj breaker and current adj transformer same varistor	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
33	BRS	66	circuit adj breaker and current adj transformer same varistor	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
34	BRS	0	circuit adj breaker and current adj transformer near varistor	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB

	Time Stamp	Comments	Error Definition	Errors
18	2004/06/14 14:20			0
19	2004/06/14 14:20			0
20	2004/10/15 13:57			0
21	2004/10/15 13:55			0
22	2004/10/15 14:05			0
23	2004/10/15 14:08			0
24	2004/10/15 15:21			0
25	2004/10/15 15:21			0
26	2004/10/15 15:32			0
27	2004/10/15 15:23			0
28	2004/10/15 15:25			0
29	2004/10/15 15:33			0
30	2004/10/15 16:38			0
31	2004/10/15 16:39			0
32	2004/10/15 16:39			0
33	2004/10/15 16:40			0
34	2004/10/15 16:39			0

	Type	Hits	Search Text	DBs
35	BRS	13	circuit adj breaker same current adj transformer same varistor	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB

	Time Stamp	Comments	Error Definition	Errors
35	2004/10/15 16:40			0